Date



# Republic of the Philippines GENERAL SANTOS CITY WATER DISTRICT

E. Fernandez Street, Barangay Lagao General Santos Telephone No.: 552-3824; Telefax No.: 553-4960 Email Address: gscwdprocurement@yahoo.com

### **REQUEST FOR QUOTATION**

DATE:

7/9/2024

RFQ #:3-0724-025

SUPPLIER: ADDRESS: TELEPHONE NO. : TIN NO. :				
Dear Sir/Madam,				
stating the sl representative	te your lowest price on the item/s listed by nortest time of delivery and submit you not later than $\frac{7/13/2024}{}$ , PIs. furnish terms and conditions contained therein.	pelow sub r quota this off	bject to tion dul fice the	general condition y signed by you following article
2. Do not a 3. If Techn (supplier /	sh this Request for Quotation duly, correctal lter the contents of this form in any way. ical Specifications/ Terms of Reference is p service provider) must indicate and signify n the specification.	provided	, prospec	t bidder
ITEM NO.	DESCRIPTION	QTY.	UNIT	UNIT PRICE
1	LABOR AND MATERIALS: BODY REPAIR AND PAINTING INCLUDING BODY MARKINGS/STICKER & LOGO-ABC-ABC: PHP 150,000.00 ########## nothing follows #########	1	LOT	P
Date of Delivery: Price Validity : Mode of Payment:				
Place of Delivery: *****No partial de Note: 6% WITHHOLDI PR NO.: 0624-011	livery allowed****			
Requested by:		Price quoted by:		
ANDREW H. NADAL	RELA		Supp	lier



# Republic of the Philippines GENERAL SANTOS CITY WATER DISTRICT

E. Fernandez St., Lagao, General Santos City Telephone No. 552-3824 / 554 – 7231; Telefax No. 553 – 4960

Email Address: gscwaterdistrict@yahoo.com

June 6, 2024

# **SCOPE OF WORK**

Body repair and painting of Foton Dump truck SAA-5101 including body markings/sticker and logo

#### **Cowling Repair and Align:**

- Flooring 2mm (checkered plate)
- Wheel base Accelerator Pedal
- Tire Box
- Step board
- Glove Box
- Front chassis
- Under chassis

#### **Trunk Repair:**

- Flooring/floor Joist
- Hinges
- Rear Bumper
- Rear Fender
- Tail Light Bracket

### **Body Wash-over paint:**

- Cowling
- Trunk
- Under Chassis
- Rim

#### **Upholstery:**

- Chair
- Door
- Panel

## **Replacement Parts:**

- 2 Pcs Corner Light Assembly L/R
- 2 Pcs Bumper Light Assembly L/R
- 2 Pcs Tail Light Assembly L/R

Prepared by:

Darwin Dave D. Sarsale, RMME
Administration Services Assistant-A

Noted by:

GSPMMD Department Manager-A

n